


LEFT SIDE VIEW


FRONT VIEW WITH DOOR CLOSED

FRONT VIEW WITH DOOR REMOVED

RIGHT SIDE VIEW




CHASSIS LAYOUT



NOTE:

REFER TO DATA SHEET TO SEE WHICH OPTIONS ARE PRESENT.



portion of RIGHT SIDE VIEW with optional tag

F	OPTIONAL PUMP CHANGED	GAR	5-27-05	THERMCO INSTRUMENT CORPORATION LA PORTE, INDIANA USA	S. O. NO.: DRAWN BY: DB APPROVED BY: SUPERSEDES: DRAWING NUMBER: 2-10941
E	REPLACED PWR SUP 7805 WITH NEW ASSY INCLUDING NEW FUSE INFO (FUSE WAS 0.5 AMP); 115 WAS 110; ADDED "OR 100 VAC TO 115 VAC"; ADDED LABELS FOR POWER SWITCH AND ZERO POT; ADDED SAMPLE GAS INLET INFO; ADDED SPAN POT CALIBRATION SCREWDRIVER INFO.	GAR	5-13-02		
D	ADDED OPTIONAL TAGS	GAR	3-11-99		
C	14 3/4 WAS 14 1/2	DMR	10-27-95		
B	ADDED DIMENSION INFO	BY	DATE		